



## Occupational Safety and Health Administration

Inspection Number	1. Photo ID No.	2. Date/Time	3. Citation Number	4. Item Number	5. Instance No.
<b>1148200</b>	<b>8830, 8831</b>	<b>5/18/2016</b>	<b>1</b>	<b>1</b>	<b>1</b>



Komatsu PC350-8 Hydraulic Excavator that was being towed by the dozer



Location of the Copperhead Shackle WLL25T CA1-1/34A attached to the bucket of the excavator.  
Note: The 4" X 20' synthetic sling that broke free from the shackle during towing operation.